

APPENDIX - VIII

PROFORMA FOR SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

No. 109

Dated: 3/6/2025

It is certified that an inspection team headed by Mrs./Miss/Mr. Pratiksha Mehar DWTL Sub.Engg.PHE, Sub. Dn. Office, Champa, Chhattisgarh (Name of Officers with Designation) from PHE Sub. Dn. Office, Champa, Chhattisgarh (Name Of Department/Office) inspected the Dev Public School Basantpur, Birra Village – Basantpur (Birra), Block-Bamhndih, District – Janjgir-Champa Pin Code – 495661 (Chhattisgarh) India (Name & Address of the school) on 10.06.25 (Date of Inspection) and Found that the Dev Public School (Name of School) has safe drinking water facilities for the students and members of staff of the institution and is maintaining the hygienic sanitation condition in the school building & the campus as per norms prescribed by the Central/State/U.T. Govt.

The above is valid for a period of **One Year**.



Signature with Seal


Name Pratiksha Mehar

Designation Incharge officer,
DWTL & Sub.Engg. PHE Sub. Dn. Office,
Barpali Chowk Champa (C.G.)

To,

The Principal
Dev Public School Basantpur, Birra
Village – Basantpur (Birra)
Block- Bamhndih, District – Janjgir-Champa (C.G.)
Pin Code – 495661 (Chhattisgarh) India


Director
Lakshmi Kumar Chandra
Mahevidyalay, Basantpur


PRINCIPAL
DEV PUBLIC SCHOOL
BASANTPUR (BIRRA)